

ASSEMBLY INSTRUCTIONS

Thank you for your purchase of one of many fine products designed & manufactured by UPC. We have made every effort to make your assembly easy, clear & hassle free. For more information or if you have any questions contact customer service at 1-800-859-7442.


PARTS BAG UPC 1453A Icon 72 Pocket Spinner

PART	Quantity	Reference
Push Pin	13 (1 extra)	Α
Long Trusshead Screw	6	В
Connector Bolt	4	С
Short Trusshead Screw	4	D
Hex Wrench	1	E
Header Clip	1	F


TOOLS REQUIRED: #2 Phillips Screwdriver

PARTS LIST


PART
Top Cap
Tower Panel
Spinner Plate Assembly
Base
X-Base Lower
X-Base Upper
Pockets




Quantity 1 3 1 1	Reference G H I J K
1 72 2	L M N
	\bigcirc











■ Watch the Instructional Video!

http://goo.gl/Z3AAcf

If you have any questions please call: UPC Customer Service

1-800-859-7442 Design & Manufacture upcdisplays.com


Revised 10/24/16


U.S. PATENT NO. 8,534,472 If you have any questions please call: UPC Customer Service

1-800-859-7442 Design & Manufacture upcdisplays.com


ASSEMBLY

1 Insert X-Base Upper (L) into X-Base Lower (K) as shown below.






Attach Base (J)
to X-Base
Assembly (K/L) using
(4) Connector Bolts (C).







ASSEMBLY

Spin and align the large holes in Spinner Plate with Spinner.











ASSEMBLY

Attach Spinner Plate
Assembly (I) to
X-Base Assembly
by using (1) Short
Trusshead Screw (D)
through large screw hole in
Spinner Plate (I) to hole in
X-Base Assembly.
DO NOT tighten
completely!




Turn Spinner Plate Assembly (I) 90° to continue attachment to X-Base Assembly, slight positioning adjustment may be necessary to find hole. To attach Spinner Plate (I), use 2nd Short Trusshead Screw (D) through large hole to corresponding hole of X-Base Assembly.

2nd Short Trusshead Screw 7 Repeat Step 6 for attaching Spinner Plate Assembly (I) to X-Base Assembly using 3rd & 4th Short Trusshead Screws (D). Tighten all screws





STOP! If you are installing casters, please refer to instruction sheet **#14532** enclosed in your caster kit.




1-800-859-7442

Design & Manufacture upcdisplays.com


ASSEMBLY

This step will support Tower Panel
Assembly (H) up for installation to Base
Assembly. Insert (2) Tower Helpers (N)
in-between Spinner Plate Assembly (I) and
Base (J), as shown below.





Align corresponding holes and set the Tower Panel Assembly (H) onto the Base Assembly.

(11)




- Secure Tower Panel Assembly (H) to Base Assembly at middle holes of Tower Panel Assembly. Attach Tower Panels to Spinner Plate edge with (3) Long Trusshead Screws (B). DO NOT tighten completely!
- Continue to secure Tower Panel
 Assembly (H) to Base Assembly at
 corner holes of Tower Panel Assembly.
 Attach panels to Spinner Plate edge with
 (3) Long Trusshead Screws (B). Tighten
 all (6) securely.






1-800-859-7442 Design & Manufacture upcdisplays.com

ASSEMBLY





15) Peel m

Peel masking off **Header**Clip (F) and secure to the center
of the **Top Cap (G)**. Lower **Top Cap (G)** on to the top
of the **Tower Panel Assembly (H)**.

(16) king the

Attach **Pockets (M)** by hooking the tabs into the vertical slots in the **Tower Panels (H).**

Lock bottom tongue of **Pockets (M)** into the horizontal slots on the **Tower Panels (H).**

Each vertical slot holds two **Pockets (M)** side-by-side.

